# FLUKE <sup>®</sup>

# 561

# Infrared Thermometer

**Users Manual** 

PN 2562924 February 2006 Rev.2, 9/07 © 2006, 2007 Fluke Corporation, All rights reserved. Printed in China. All product names are trademarks of their respective companies.

#### LIMITED WARRANTY AND LIMITATION OF LIABILITY

This Fluke product will be free from defects in material and workmanship for two years from the date of purchase. This warranty does not cover fuses, disposable batteries, or damage from accident, neglect, misuse, alteration, contamination, or abnormal conditions of operation or handling. Resellers are not authorized to extend any other warranty on Fluke's behalf. To obtain service during the warranty period, contact your nearest Fluke authorized service center to obtain return authorization information, then send the product to that Service Center with a description of the problem.

THIS WARRANTY IS YOUR ONLY REMEDY. NO OTHER WARRANTIES, SUCH AS FITNESS FOR A PARTICULAR PURPOSE, ARE EXPRESSED OR IMPLIED. FLUKE IS NOT LIABLE FOR ANY SPECIAL, INDIRECT, INCIDENTAL OR CONSEQUENTIAL DAMAGES OR LOSSES, ARISING FROM ANY CAUSE OR THEORY. Since some states or countries do not allow the exclusion or limitation of an implied warranty or of incidental or consequential damages, this limitation of liability may not apply to you.

> Fluke Corporation P.O. Box 9090 Everett, WA 98206-9090 U.S.A.

Fluke Europe B.V. P.O. Box 1186 5602 BD Eindhoven The Netherlands

11/99

# Table of Contents

## Title

## Page

Introduction	1
Contacting Fluke	1
Safety Information	2
Features	
Display	4
Button's and Connector	5
How the Thermometer Works	6
Operating the Thermometer	6
Locating a Hot or Cold Spot	6
Distance and Spot Size	6
Field of View	7
Emissivity	7
Switching Between °C and °F	8
Using the Contact Temperature Probe	9
HOLD	10
Maintenance	10
Changing the Battery	10
Cleaning the Lens	10
Cleaning the Housing	10
Troubleshooting	11
CE Certification	11
Specifications	11

## List of Tables

#### 

# List of Figures

## Title

Figure

## Page

1.	Symbols and Safety Markings	
2.	Infrared Thermometer	4
3.	Thermometer Display	5
	Locating a Hot or Cold Spot	
5.	Distance and Spot Size	7
6.	Field of View	7
7.	Switching Between °C and °F	9
8.	Connecting the Temperature Probe	9

# 561 Infrared Thermometer

## Introduction

The Fluke 561 Infrared Thermometer (hereafter, the Thermometer) can determine the surface temperature by measuring the amount of infrared energy radiated by the target's surface or by contact using a thermocouple probe. The Thermometer was designed specifically for use in heating, ventilating, and air conditioning (HVAC) applications. This manual covers all versions of the the Fluke 561.

## **Contacting Fluke**

To contact Fluke, call one of the following telephone numbers:

USA: 1-888-44-FLUKE (1-888-443-5853) Canada: 1-800-36-FLUKE (1-800-363-5853) Europe: +31 40 267 5200 Japan: +81-3-3434-0181 Singapore: +65-738-5655 Anywhere in the world: +1-425-446-5500 For USA Service: 1-888-99-FLUKE (1-888-993-5853)

Or, visit Fluke's Web site at <u>www.fluke.com</u>. To register your product, visit <u>register.fluke.com</u>.

## Safety Information

#### <u>∧</u>∧Warning

- A Warning identifies conditions and actions that pose hazards to the user. To avoid electrical shock or personal injury, follow these guidelines:
- 🛕 Do not point laser directly at eye or indirectly off reflective surfaces.
- Before using the Thermometer inspect the case. Do not use the Thermometer if it appears damaged. Look for cracks or missing plastic.
- Replace the batteries as soon as the battery indicator (1) appears.
- Do not use the Thermometer if it operates abnormally. Protection may be impaired. When in doubt, have the Thermometer serviced.
- Do not operate the Thermometer around explosive gas, vapor, or dust.
- Do not connect the optional external probe to live electrical circuits.
- To avoid a burn hazard, remember that highly reflective objects will often result in lower than actual temperature measurements.
- Do not use in a manner not specified by this manual or the protection supplied by the equipment may be impaired.

#### **∆**Caution

To avoid damaging the thermometer or the equipment under test protect them from the following:

- EMF (electro-magnetic fields) from arc welders, induction heaters, etc.
- Static electricity.
- Thermal shock (caused by large or abrupt ambient temperature changes- allow 30 minutes for the Thermometer to stabilize before use).
- Do not leave the Thermometer on or near objects of high temperature.

Table 1 and Figure 1 show various symbols and safety markings that are on the Thermometer and in this manual.

Symbol	Explanation
≙	Risk of danger. Important information. See Manual.
	Hazardous voltage. Risk of electrical shock.
$\widehat{}$	Warning. Laser.
CE	Conforms to requirements of European Union and European Free Trade Association (EFTA).
X	Do not dispose of this product as unsorted municipal waste. Go to Fluke's web site for recycling information.
Ĥ	Battery
<b>MC</b> 沪制01120009号	Chinese manufacturing mark for products manufactured in the Peoples Republic of China (PRC).

#### Table 1. Symbols

## Infrared Thermometer Features



Figure 1. Symbols and Safety Markings

efh010f.eps

## Features

The Thermometer includes:

- Single-spot Laser Sighting
- Backlit Display
- Hard Case
- Current Temperature Plus MIN, MAX, DIF Temperature Displays
- Easy Emissivity Selector
- Type-K Thermocouple
- Two AA Batteries

Thermometer features are shown in Figure 2.




Figure 2. Infrared Thermometer

efh007f.eps

## Display

The primary temperature display reports the current or last IR temperature read until the 7-second hold time elapses.

The secondary temperature display reports current thermocouple temperature when a type-K thermocouple is attached. When a thermocouple is not connected, the small temperature display reports a choice of maximum, minimum, or difference between maximum and minimum temperature.

You can toggle through the minimum, maximum, and difference IR temperatures anytime the display is on. The MIN, MAX, and DIF temperatures are constantly calculated and updated when the trigger is pressed. After the trigger is released, the MIN, MAX, DIF temperatures are held for 7 seconds.

Note

#### When the battery is low, 🕆 appears on the display.

The last selection (MIN/MAX/DIF) is maintained on the secondary display even after the Thermometer has been turned off, providing the batteries have not failed.

## Infrared Thermometer

Buttons and Connector

	1 2 3 3 3 3 4 -)8888.8 5 0 0 0 0 0 0 0 0 0 0 0 0 0	
1	Laser "On" symbol	
2	SCAN or HOLD	
3	°C/°F symbol (Celsius/Fahrenheit)	
4	Primary temperature display	
5	5 Secondary temperature display	
6	6 Emissivity LO, MED, HI	
7	Temperature values for the MIN, MAX, DIF, KTC. KTC indicates the thermocouple temperature.	
8	Low Battery symbol. Appears when the battery charge is < 25%.	

#### Figure 3. Thermometer Display

## **Buttons and Connector**

Button/ Connector	Description
Ant max	Press and then press 🖨 to toggle between the MIN, MAX, and DIF options.
	The 🚔 button is used to show the MIN, MAX, and DIF functions in the secondary display, whichever was pressed most recently.
E	Selects the emissivity setting. You can toggle between LO (0.3), MED (0.7), or HI (0.95) using $\textcircled{\clubsuit}$ .
	K-type thermocouple probe used to make contact temperature measurement.

## How the Thermometer Works

Infrared thermometers measure the surface temperature of an opaque object. The Thermometer's optics sense infrared energy, which is collected and focused onto a detector. The Thermometer's electronics then translate the information into a displayed temperature reading which appears on the display. The laser is used for aiming purposes only.

## **Operating the Thermometer**

The Thermometer turns on when you press the trigger. The Thermometer turns off when no activity is detected for 7 seconds.

To measure temperature, aim the Thermometer at the target, pull and hold the trigger. Release the trigger to hold a temperature reading.

Be sure to consider distance-to-spot size ratio and field of view. The laser is used for aiming only.

#### Locating a Hot or Cold Spot

To find a hot or cold spot, aim the Thermometer outside the target area. Then, slowly scan across the area with an up and down motion until you locate the hot or cold spot. See Figure 4.




Figure 4. Locating a Hot or Cold Spot

#### efh014f.eps

#### **Distance and Spot Size**

As the distance (D) from the target being measured increases, the spot size (S) of the area measured by the unit becomes larger. The spot sizes indicates 90 % encircled energy. The maximum D:S is obtained when the Thermometer is 900 mm (36 in) from the target resulting in a spot size of 75 mm (3 in). See Figure 5.





Figure 5. Distance and Spot Size

#### Field of View

Make sure that the target is larger than the spot size. The smaller the target, the closer you should be to it. See Figure 6.







#### Emissivity

Emissivity describes the energy-emitting characteristics of materials. Most organic materials and painted or oxidized surfaces have an emissivity of about 0.95.

If possible, to compensate for inaccurate readings that may result from measuring shiny metal surfaces, cover the surface to be measured with masking tape or flat black paint (< 148 °C/300 °F) and use the high emissivity setting. Allow time for the tape or paint to reach the same temperature as the surface beneath it. Measure the temperature of the tape or painted surface.

If you cannot paint or use tape, then you can improve the accuracy of your measurements with the emissivity selector. Even with the emissivity selector, it can be difficult to get a completely accurate infrared measurement of a target with a shiny or metallic surface. Experimentation, using the probe to determine benchmark temperatures, and experience will help you choose the best setting for specific measurements.

The Thermometer has three emissivity settings: low (0.3), medium (0.7), and high (0.95). Refer to Table 2. The reference to emissivity settings in the table are suggestions for typical situations. Your particular situation may differ.

Measured Surface	Switch Setting	Measured Surface	Switch Setting
Aluminum		Iron, Cast	
Oxidized	Low	Oxidized	High, Medium
Alloy A3003		Unoxidized	Low
Oxidized	Low	Molten	Low
Roughened	Low	Iron, Wrought	
Brass		Dull	High
Burnished	Low	Lead	
Oxidized	Low	Rough	Low
Copper		Oxidized	Low, Medium
Oxidized	Medium	Molybdenum	
Electrical Terminal Blocks	Medium	Oxidized	Low, Medium
Haynes		Nickel	
Alloy	Medium	Oxidized	Low
Inconel		Platinum	
Oxidized	High, Medium	Black	High
Sandblasted	Medium	Steel	
Electoropolished	Low	Cold-Rolled	High
Iron		Ground Sheet	Medium
Oxidized	High, Medium	Polished Sheet	Low
Rusted	Medium	Zinc	
		Oxidized	Low

Table 2. Surface Emissivity

#### Switching Between °C and °F

Open the battery compartment and locate the switch positioned between the left side of the battery near the Thermometer wall. To toggle between °C and °F, use a small screwdriver or paper clip to move the switch to the desired position. See Figure 7.

#### Infrared Thermometer Operating the Thermometer




Figure 7. Switching Between °C and °F

efh012f.eps

#### Using the Contact Temperature Probe

## **∧** ∧ Warning

# To avoid electrical shock or personal injury, do not connect the optional external probe to live electrical circuits.

Connect the probe to the input on the top of the Thermometer. The probe temperature and KTC appears in the secondary display. The live infrared temperature continues to show in the primary display. Connect the temperature probe as shown in Figure 8.

Note

With the probe inserted, the Thermometer stays on for 10 minutes (with laser off) after the trigger is released.




Figure 8. Connecting the Temperature Probe

Table 3 lists recommended Fluke temperature probes for use with the Thermometer:

Probe	Usage
80PK-25	The piercing probe is the most versatile option. Good for checking air temperature in ducts, surface temperature under carpets/pads, liquids, thermometer wells, vent temperatures, and for penetrating pipe insulation.
80PK-1	The general purpose bead probe is an alternative, for quick, accurate surface temperatures and air temperatures within ducts, vent temperatures.
80PK-8	Pipe clamp probes (2) are essential for tracking continuously changing temperature differentials on hydronic tubing and pipe loops, and good for quick, accurate refrigerant temperatures.
80PK-26	The tapered probe is a good general-purpose gas and surface probe, with a good length and low mass tip casing for faster reaction to surface and air temperatures.
80PK-9	The insulation piercing probe provides a sharp tip to pierce pipe insulation and flat probe tip for good surface thermal contact, air temperatures within ducts, and vent temperatures.
80PK-11	The Velcro pipe probe is a convenient way to attach a thermocouple to a pipe while keeping hands free.

Table 3	Recommended	Temnerature	Prohes
I abic J.	necommenueu	remperature	FIUNCS

#### HOLD

The display will remain activated for 7 seconds after the trigger is released. HOLD appears in the upper middle of the display. When the trigger is pulled again, the Thermometer will begin measuring in the last function selected.

## Maintenance

#### **Changing the Battery**

To install or change the two AA batteries, open the battery compartment and insert the batteries as shown in Figure 2.

#### **Cleaning the Lens**

Blow off loose particles using clean compressed air. Carefully wipe the surface with a moist cotton swab. The swab may be moistened with water.

#### **Cleaning the Housing**

Use soap and water on a damp sponge or soft cloth.

## **∆**Caution

To avoid damaging the Thermometer, do NOT submerge it in water.

## Troubleshooting

Symptom	Problem	Action
(on display)	Target temperature is over or under range	Select target within specifications
Ê	Low battery	Replace battery
Blank display	Possible dead battery	Check and/or replace battery
Laser does not work	1. Low or dead battery	1. Replace battery
	2. Ambient temperature above 40 °C (104 °F)	2. Use in area with lower ambient temperature

## **CE Certification**

The Thermometer conforms to the following standards:

- EN61326-1 EMC
- EN61010-1
- EN60825-1 Safety

Certification testing was conducted using a frequency range of 80 to 1000 MHz with the instrument in three orientations.

## **Specifications**

#### Infrared

Measurement Range	40 °C to 550 °C (-40 °F to 1022 °F)
Spectral Range	
Accuracy	±1 % or ±1 °C (2 °F); < 0 °C (32 °F),
	± 1 °C (2 °F) ± 0.1°/1°
	(Assumes ambient operating temperature
	of 23 to 25 °C (73 to 77 °F))
Repeatability	$\pm$ 0.5 % of reading or $\pm$ 1°C (2 °F)
Display Resolution	0.1 °C (0.1 °F)
Secondary Display Information	Maximum, Minimum, Differential, KTC
Response Time (95 %)	
Distance to Spot (D:S)	
Emissivity Adjustment	
	high (0.95)

#### **Contact Probe Input**

Input Temperature Range	40 °C to 550 °C (-40 °F to 1022 °F)
Input Accuracy	Input accuracy $\pm$ 1.1 °C ( $\pm$ 2 °F)
Display Resolution	1 °C (1 °F)

#### Laser

Sighting	Single point laser
	Class 2 (II) operation; Output < 1 mW,
	wavelength 630 to 670 nm

### Wrap Thermocouple Probe (model-specific)

Туре	Type K with miniconnector and Velcro strap, ASTM E230-03 Standard Tolerance
Measurement Range	0 °C to 100 °C (32 °F to 212 °F)
Accuracy	± 2.2 °C (4.0 °F)
Total Length	505 mm (20 in) cable terminated with a Type K thermocouple inside a 495 mm (19.5 in) nylon Velcro cuff
Bead Thermocouple Probe (model-specific)	
Туре	Type K with miniconnector
Measurement Range	40 °C to 260 °C (-40 °F to 500 °F)
Accuracy	± 1.1 °C (2.0 °F) from 0 °C to 260 °C (32 °F to 500 °F). Typically within 1.1 °C (2.0 °F) from -40 °C to 0 °C (-40 °F to 32 °F)
Cable Length	1 m (40 in) terminated with Type K thermocouple beads
Electrical	
Power Supply Power Consumption	· · · · · · · · · · · · · · · · · · ·
Physical	
Weight Size	
Environmental	
Operating Temperature Range	( )
Relative Humidity	0 to 90 %, noncondensing up to 30 °C (86 °F)
Storage Temperature	20 °C to 65 °C (-4 °F to 150 °F)
Optional Accessories	Soft Case